

SECTION 27-2-15

NORTH - SOUTH
WESTING AC SECTION 22-C

N
↑

Description of the West line in Milk
 Company property calls for the line to be parallel to
 the West line of Section 27, to be parallel the fence must
 be at the location of the ~~clothes~~ ^{which does not check the P.C. line} line, the Iron Pipe
 at the south end or the length of the southerly line
 as given in the description

FOUND IRON PIN AT SOUTH
CORNER ON FENCE LINE _____

Plot of survey of land located in the southwest 1/4
of section 27, T2N R15E of Malworth county, Wisconsin

May 1947

Floyd T Jensen
County Surveyor
~~and~~