

7 8/20/30 Como Beach

Survey of N. line Lake
and Beech road. Lots
Found iron stks. as follows
SW cor 4290 4268, 4267 + 4288
Checked location of all stks
and lined in and set new
and ^{at S.E. cor} 4291. N. line L.S.
E. Part runs straight W.
Block 73, between Beech
on Lake Como
Measured ~~2~~ 2.7 line
W. line lot 4300, 89.11
S.W. cor. 4300 to N.W. cor.
Front or E line 4286, 17.5
4296 to 4300 each 20.02

Shore Drive between Acacia Road
4291-4300
S.E. cor. 4265, S.E. cor. 4268.
+ 4296. 4296. reset. also 4290
re-setting all bent over wrongly set
iron stks at S.W. cor. 4300, 4295.
Drive angles at S.W. cor. 4286.
part curves
Road & Acacia Road fronting
Lot 4281 91.01'
Ctr. line between lots 4285, 4286, 74.52'
4300, 89.11'
4291-4295, 20.7 each,

Lots 4291 to 4300 Lake Como Beach

217-111-Sk

2

8/6/30 Survey requested
Lots 11981-11982
canceled

by owner, Mr. Peterson for same
8214 Dandelion Road, Black
same day

8/11/30, call by telephone
4350, Sect. 86.
Request for com-
munication first,
Failed to get address,
Lots reached by
Green Road W. of Tanana Road

for survey of lots 4349 &
Green Road, Pell Lake.
municipal first,
a Mr. Hough,
road W. of Lake, past L. Kimball,
Road

8/15/30 Survey for
Karlou, Ave. Chicago
Survey of Lots 9750
Drive and Robin Road
S. E. Cor. Blocks 119 and
of B. 178, also iron
+ 9749 surveyed as
and all O.K. except
2' off corrected &
corners Blaitters 5
as one parcel by
iron stks set at
1. at S.E. Cor.
Surveyor O.K.

Mrs. B. Blaitters 1648 N.
Ill.
- 9754, B. 179, Cor. Whittier
Found iron stks as follows.
S.W. Cor. B. 119, also N.W. Cor.
stks. at all cor's of lot 9788
one parcel. Checked all
S.E. Cor. of lot 9788 which was
used there in locating
lot parcel. 5 lots survey
request of owner,
3 corr of 5 lot parcel,
was set by original

Price \$5.50
paid
cash

Reached by driving from Route 12, thru
clubhouse road to clubhouse, thence
to L.S. Drive. Follow L.S.D
son club Acacia Road

to Whittier, W. on Whittier
2 sections to Robin

Lots 9750-9754

217-112-sk