

8/14/25: Survey for
 Phillips Subdivision
 on east & north sides
 parallel to and 168'
 street, from south
 to R.R. right of
 First determined West
 stakes and distances
 of East Street at
 N. line of alley
 checked except stake
 far west and at
 too far west. New
 line in S. line of Block
 too far south by 45 ft.
 Measured N. on S. line
 O.K. Measured South
 edge of walk also
 line Block 3. lined
 W. from S.E. cor. lot B.
 measured W. 60' farther
 stake S.W. cor. lot 1.
 Stake at 168' is 1.2' N. of
 5.1' west of W. side bottom
 sth. at S.W. cor. lot 1. is in line

S. C. Ford.
 to determine boundary lines
 of a strip 60' wide
 West of West line of West
 line of lot Block 8. South
 way.
 line of West by checking
 from stakes at West line
 S. line of Darwin Street and
 in Block 4. stakes all
 at N.E. cor. Block 4 12' too
 S.E. cor. of Block 3. 5"
 iron stake set at last named point
 2. But this was found to be

Block 3 323' from S.E. cor
 on West St. 260' from S.
 260' S. from walk on W.
 in with transit, measured
 3. 168' and set iron stake
 on same line and set iron
 also set iron sth at S.E. cor

bottom board to fence and
 board to E. fence

with N. side bottom board.
 5.5' W. of 4" S. E. & 4.5' W. cor. post,

2 8/15 S. C. Ford continued

Finished survey of
Set transit at S.
and lined in and
line at rt. angles
intersect R.R. line
W. of ~~west~~ East line
proved exact, measured
in R.R. fence line.
Wit. 7.1' west of iron
3.9' N.W. " R.R.

True east line of
of fence at N. end
South half of East line
North half shows old
fence is built,

lines as required
end of E. line of Block 3
made point opp. where a
to said E. line would
at required distance 168'
of Block 3, distance estimate
168' and set iron stake
maul mark in post brace
fence post,

Mrs. Harris lot is 5.1' west
and 7.1' west at South end,
old fence still standing
fence post holes where new