

MIRAMAR SUBDIVISION. 1<sup>ST</sup> ADDITION - BLOCK 19  
TOWN OF EAST TROY. WALWORTH COUNTY. T4N. R18E. WISCONSIN  
SECTION 10



WALNUT STREET

All pipes except A are 1" I.P. A has a split and curved top. Location surveyed is the bottom portion of this pipe.


All points have been computed in a local grid of coordinates. The grid axis of Y has a bearing of  $N 8^{\circ} 50' 43'' E$  as related to the recorded bearing of Walnut Street Centerline which is recorded in the Office of the Deeds of Walworth County. Miramar Suddington

Points M and L were not located. More research and survey is needed to ascertain their exact location due to obstacles. A small outbuilding (pump house!) seem to encroach slightly over the boundary line, in lots 6 and 19, from adjacent lot 20. at point L; its location also needs to be ascertain by additional survey. Remediation areas in lot 6 were plotted from the report from testers / Dale's Drafting service and are only informative

found a  
disturbed I.P. here  
not surveyed

PLUM DRIVE

Surveyed and drawn by Albert E. PENNEQUIN, Registered  
Land Surveyor, as requested by Mr William H. Kingston of  
KINGSTON AND SMART, Attorneys at Law in Mukwonago, Wisc.  
Elkhorn, Sept. 16, 1979



ELM  
STREET