around 3 Found To be 3/4 incl short on west end. nak, asto Location, North wall & South wall as Tores about 2' too far into Ea measured los N. W. Cor, of 39. Sahe Menera Highlids

117-935 lk

December 22,1938.

Mr. Herman Raltsch,

Chicago, Ill.,

Dear Sir; Te surveyed your lot number 53 in the Lake Geneva MICHLANDS BUBBIVISION on the South side of Lake Geneva and fouring everything as you told us and as shown of the plat we got from Trinke. That yellow house you mentioned is on lot 39 fronting on OAKDALT ROAD. Has a concrete wall all around it. To checked that of lot all ar und. That let is cornerwise to your lot that is, the N.W. corner of that lot is your Southeast Cor. and is O.K. His East line is two feet over in Oakdale Road but that does not matter. The North wall of his lot bulges in the middle quite a little but that does not in any we 4 affect your lot. Your lot is 50 feet North and South and 100ft. East and West and is O.K.in every respect. We set Iron and woods stakes at the N.W.S.W. and N.E. Cors of your lot and the S.E. Cor. of your lot is the N.W.Cor.Of his wall.

There is a large oak tree near the front of your lot on the South line, the Arth side of which comes just to your South line. I know it is there for I fell and struck my head against it. The South Side of that tree is the South line of your lot, so everything is flear. Gur bill for the entire work and plat is Five Dollars.

Thank you for the work.

Yours truly .

J.G.Skeels.

Hr. Watten HERMAN RALTSCH, Dr. to J.G. Skeols For survey of lot 55, LAKE GENEVA HIGHLANDS

Paid in fully Skeds

35.00