

GEORGE T. DUNHAM
SURVEYING & SUBDIVIDING
DELAVAN, WISCONSIN

Fence Post at Correct Corner.
Iron Pipe located 0.53' SE
of Correct Corner.

