

77 8/10/22

Survey for O.D.
W. $\frac{1}{2}$, N.W. $\frac{1}{4}$, S.W. $\frac{1}{4}$
located and witnessed

Found old wood stake
and verified it by former
bar driven about 2" below
Witness } 24 $\frac{3}{4}$ ' East to a 2" iron stake
S. 70° W. 25.3' to blaze on
S 65° E 27.5' to " "

Traced a line of stakes
100' apart and set Tally
line 660 $\frac{1}{4}$ ' and set iron
stake 7 or 8' east of
Measured south on east
and set wood stake
fence. (but not proven)

Measured south on west
and set iron stake
Witness } West 24' to top wire
S. 45° E. 45' to blaze
fence

But line and measured
Distance 660 $\frac{1}{4}$ ' and set
Witness } 6' south and 1' west of
N. 15° E. 32' to 4" B.O.
N. 60° W. 21' to Double B.O.

Set wood stake at S.W. cor.
of iron stake at $\frac{1}{8}$ cor.

Measured south 64' from stake
previous error! Wit. N. 18' to
N. 40° W. 13'
Re-set stake as above at N. cor.

J. Notter.

33-2-17 20 Acres
W. $\frac{1}{4}$ cor. Sect. 33,
(iron stake gone) in new road
Witness. Set $\frac{3}{8}$ " x $3\frac{1}{2}$ " steel
surface of road.

7" H. maple
4" Bitter Hickory
formerly set on north line
stakes. measured east on this
stake $\frac{3}{4}$ " and 2" by 2 $\frac{1}{2}$ " wood
fence.

line 1323' ($\frac{1}{2}$ of 1/4 line 2646')
about 6' south of Lucy-Cronin
as to E & W location

line 1323' from $\frac{1}{4}$ cor.
in west wheel track new road
in fence
on 6" poplar about 4' south
of an old line fence post,
thru on S. line of above tract.

iron stake
new cor. post
blazed

10" x 12"

on E. line New highway 24 $\frac{3}{4}$ ' east
in west track new highway ^{of old same place}
set for N.W. cor. Hanson lot, correcting
Double B.O. 4" x 5" blazed
to 3" B.O.
stake 4 $\frac{3}{4}$ " S. of cor. post.
Hanson. No wit. These are wood stakes

- Certified Surveys 577, 778 & 1011

217-144-sk