

- = Badly bent iron pipe found
- 1 1/4" iron pipe reset
- ✱ = 1/2" Iron Pipe Set
- Ø = 3/4" Iron Pipe Found
- = 1" Iron Pipe Found
- = 1 1/2" Iron Pipe Set

SURVEYING & SUBDIVIDING
DELAN, WISCONSIN 53115

BELOIT STREET

COUNTY TRUNK HIGHWAY "X"

Found bent iron pipe. Did not correct

154.00

132.00

36.3

11.9

35.9

39.6

N59°10'E 132.00

38.5

44.3

24.4

House

27.3

14.7

deck

24.3

24.3

13.4

45.6

S28°04'E 184.00

52

53

54

51

50

49

48

47

46

45

44

43

Total

N59°10'E 132.00

Turner Street (Not improved)

132.00

Scale - 1" = 20'

● = Badly bent iron
1 1/2" Iron pipe r
✱ = 1/2" Iron Pipe Set
Ø = 3/4" Iron Pipe
○ = 1" Iron Pipe For
● = 1 1/2" Iron Pipe S

Survey ordered by:
Century 21 Affiliated-S
50 West Geneva
Williams Bay, WI 53191

RECEIVED
MAY 9 2003
JAR