

**SURVEYING & SUBDIVIDING
DELAYAN, WISCONSIN 53115**





- = Concrete Monument Found
- ⦿ = 5/8" Iron Rod Found
- ⌘ = 3/4" Iron Pipe Found
- ⊙ = 1/2" Iron Pipe Found
- = 3/4" X 24" Iron Pipe Set
- ◐ = 1/2" X 24" Iron Pipe Set
- ⌘ = 1 1/2" X 24" Iron Pipe Set

Survey ordered by:
Don Nichols, Realtor
308 Kenosha
Walworth, WI 53184

Walworth, WI 53184
Updating and recertification ordered by:
Tom Seibert
832 Sauganash
Fontana, WI 53125
Updating and recertification ordered by:
The Rauland Agency
118 Kenosha Street
Walworth, WI 53115

George T. Dunham
George T. Dunham, Surveyor



SC03-40
005-1503