

45' Mar 16, 1933
Survey of Lot 31 Columbia
By request of F. H. Gaggart
Lot previously surveyed
as 50' E. & W. by 150' N. W.
on N. side of Pleasant
St.

First ascertained if iron
pipe stakes set at each of
4 corners were still in
place. They were found O.K.
Measured all at rear or
N. side. 15'

Next measured distance
of N. W. & S. W. corners of base-
ment walls from W.
lot line to 7.9'

Cornice including 6" eave
gutter 5.9' E. of W. lot line
S. W. cor. of basement
wall is 26.6' N. of N. line
of sidewalk or 25.6' N.
of S. line of lot.

Sun porch is 14.3' E & W,
and 2' end is flush with
E. side of house

House extends west of
sun porch 12'
20.5' from N. line sidewalk
to S. line sun porch

house
Front walk is 16' E. of W.
line of lot. Walk 3.9' wide
19.3' from N. line of sidewalk
to 1st riser in front steps.
Sun porch extend 6' S. of
W. part of house

E. line of house is 45'
S. line sun parlor to N. line
side walk is 14.5'

Sun porch is 3.9' N. & S. and
4' E & W. railing on W. side
of steps 5 steps

Upright as 9.2' above wall
wall 2' above ground
Sun porch 8.7' above wall
that is to top of plate

Back porch 6.9' E & W.
& 3.9' N. & S. Back end of
porch is just W. of back
door. Door is central

Pleasant St. is 60' wide
driveway curb to curb
is 26' parking 17'

No walk south side of
street. No curb in front
of Lot 31 No improve-
ment on street at this

46 point
sanitary sewer in
center of st.
vacant lot on E &
on west side
18" cotton wood tree
11' W. of S. E. stake &
4' N. of side walk
18" ash leaved maple
on W. line 4'
N. of N. line side walk
See plat G. 98,