


Q

Surveyed for:

Bearings referenced to the subdivision plat.



RECEIVED  
JUL 19 2016  
By 

All rights reserved. No part of this survey plat may be reproduced or transmitted in any form by any means – graphic, electronic, or mechanical, including photocopying, tracing, or information storage and retrieval systems – without permission in writing from Douglas G. Olson, Jensen & Olson Land Surveying, LLC.

Douglas G. Olson  
Wisconsin Registered Land Surveyor - 2093

Scale in Feet  
1" = 20'

Jensen & Olson Land Surveying, LLC

45 South Wisconsin Street P.O. Box 332  
Elkhorn, Wisconsin. 53121  
Telephone (262) 723-3434  
Facsimile (262) 723-8044

**Legend**

- Found Iron Pipe
- Found Iron Rod
- ( ) Recorded Information
- Clothes line pole
- Hydrant
- ⊗ Utility Pole
- Stone Surface
- ▨ Asphalt Surface
- ▩ Gravel Surface

Sheet 1 of 1 Sheets

Job Reference Number  
**2016.013**

2016.013