

o = 1/2" Iron Rod Found
 x = 1/2" Iron Rod Found .8' below
 ground, bent, and pulled
 straightened and reset at
 surface.

Survey ordered by:
Realty World, Carmin Realtors
811 East Geneva Street
Delavan, WI 53115

Q = 3/4" Iron Pipe Found

George T. Dunham
George T. Dunham, Surveyor

