CERTIFIED SURVEYS 9, 31, 41, 56, 92 AND 93

TOWN OF BLOOMFIELD

CERTIFIED SURVEY # 9

PLAT OF SURVEY OF

A parcel of land located in the Northwest 1/4 of Section 14, T 1 N, R 18 E, Walworth County, Wisconsin



CERTIFIED SURVEY NO. 56

CERTIFIED SURVEY OF
A parcel of land located in the Northeast ¼ and the Southeast ¼ of the Southeast ¼ of Section 16, T 1 N, R 18 E, Walworth County, Wisconsin,



LENGEND
- ⊠ Iron pipe found
- ○ Iron pipe 1" x 24", 1.13 lb/lin. ft.
- ⊠ Conc, Monument found by ties

OWNER: John Creagh
Box 373
Pell Lake, Wis.

NOTE: Bearing along Cedar Road assumed North.

CERTIFIED SURVEY NO. 93

A parcel of land located in the Northwest 1/4 of Section 14, T1N, R18E, Walworth County, Wisconsin.



Bearings are based on the Wisconsin Plane Coordinate System as shown on Highway Project T04-1(21).

LEGEND
- ○ — IRON PIPE PLACED. 1" x 24" 1.13 LB./LIN. FT.
- ◎ — CONCRETE MONUMENT. 5" DIA. x 30"

CERTIFIED SURVEY NO. 92

located in the Southeast ¼ of the Southwest ¼ of Section 26, T 1 N, R 18 E, Walworth County, Wisconsin.



No contours shown as there is less than 2' variation in elevation on the parcel of land.

CERTIFIED SURVEY # 31

A parcel of land located in the Southeast ¼ of Section 13, T 1 N, R 18 E, Walworth County, Wisconsin.



CERTIFIED SURVEY No. 41

LAND LOCATED IN THE SOUTH EAST 1/4 OF SECTION 13 T.1N. R.18E. TOWNSHIP OF BLOOMFIELD, COUNTY OF WALWORTH, STATE OF WISCONSIN.



- ○ = Iron Pipe 1"x24" 1.13 lbs./ft. or larger.
- ◎ = Concrete Monument