

May 2, 1914

Survey of North + South sides
of Mrs Geo. Conants lot.

At W. 1/4 S. E. 1/4 S. E. 1/4 Sec. 26,
T. 2, N. R. 17, E.

At S. E. corner found iron stake
set by Wm Child 4' west of
corner and at N. E. corner
found another iron stake also
set 4' west of true corner

This according to Childs notes
but why this 4' deviation

At S. W. corner found an
iron stake set by Child at south
side of corner fence post.

Tested south line and found
it 656' lacking 3' Childs

says 655' (since whole south
section line is short only 65'
why should this one be 14' Childs
recrd shows the south 1/4 post
to be in center)

Set stakes along the East
& south lines using iron
stakes as set by Childs.
The north line of occupancy
found by Childs 12' short
but no stake set at N. W.
corner. Why? J. G. Skeels surveyor
B. Palmer Asst.

Conant St. & west
fence appears
to be 38' long
far east

UP-46 + 46C
UP-47 + 47B

7-444-lh