

LOCATION OF IMPROVEMENTS
WAS WANTED BY THE CLIEPTER
A-E7.01(2) OF THE WISCONSIN
ADDMINISTRATIVE CODE.

FOUND 2" IRON PIPE FOUND 3/4" REBAR

CURVE	RADIUS	LENGTH	CHORD	BEARING	DELTA
C1	1133.00'	23113'	230.73'	N3634'06'W	11'41'18'
C2	66.00'	85.03'	79.27	N1979'47"W	73'48'57"

"I hereby certify that I have surveyed the above described p operty and that the above map is a true representation thereof and shows the size and location of the property, its exterior boundaries, the location of all visible structures and dimension of a principal buildings thereon, boundary fences, apparent essements, roadways and encroachments if any."


SCALE 1'-80'

"This survey is made for the use of the present owners of the property, and also those who purchase, mortgage or guarantee the title thereto within one year from date hereof."

10/19/99 TEP/DW
PATE FIELD WORK BY



W356 S9050 Godfrey Lane P.O. Box 357 Eagle WI. 53119



(414) 594-3484 fax (414) 594-5904

THIS IS NOT AN ORIGINAL SURVEY UNLESS THE SEAL IS RED.

7EP DRAWN BY 99261 JOB NUMBER

BSU-7