



- ✶ = 1 1/4" Iron Pipe Found
- ◊ = 1" Iron Pipe Found
- = 1" X 24" Iron Pipe Set
- = 1 1/4" X 24" Iron Pipe Set

Bearings shown are those on the recorded plat of 1st Addition to Lakewood Estates Survey ordered by: R. Gray Betzer  
1813 Lake Trail  
Delavan, WI 53115

George T. Dunham  
George T. Dunham, Surveyor

