


Plat of Survey

of
Lots 1, 2 and 3 of Certified Survey Map No. 536,
recorded in Vol. 2 of Certified Survey Maps of Walworth County
on Page 379 and located in the Southeast 1/4 of Section 10,
Town 4 North, Range 18 East, Town of East Troy, Walworth
County, Wisconsin.

Surveyed for: **Joseph Glowacki**
W1076 Spleas Skoney Road
East Troy, Wisconsin. 53120



Survey date: April 19, 2002.
Revisions:

Scale in Feet
1" = 30'

Jensen & Olson Land Surveying, LLC
45 South Wisconsin Street P.O. Box 322
Elkhorn, Wisconsin, 53121
Telephone: (262) 723-3434
Facsimile: (262) 723-8044

Legend



- Found Iron Pipe in situ
- Set of Galvanized Pipe from owner
- Recorded Information
- Utility Pole
- Concrete or Box
- Asphalt Surface
- Gravel Surface

Sheet 1 of 1 Sheets.

Job Reference Number

2002.051

2002.051



Notes: 1) This survey plat is not certified unless signed and sealed in red ink.
2) This survey is subject to Wisconsin lien laws. This Plat of Survey is the notice of intent to file lien. Lien waiver required.

Copyright © 2002 by Jensen & Olson Land Surveying, LLC.
All rights reserved. No part of this survey plat may be reproduced or transmitted in any form by any means - graphic, electronic, or mechanical, including photocopying, tracing, or information storage and retrieval systems - without permission in writing from Douglas G. Olson, Jensen & Olson Land Surveying, LLC.

I, Douglas G. Olson, Wisconsin Registered Land Surveyor, do hereby certify that this survey was performed by me or under my direction in full compliance with the owner's/agent's instructions and Chapter A-E 7 of the Wisconsin Administrative Code "Minimum Standards for Property Surveys", and that this map is an accurate representation thereof to the best of my knowledge and belief.

Douglas G. Olson
Wisconsin Registered Land Surveyor - 2093